



## THE INTERNATIONAL UNION OF MARINE INSURANCE & DPS AFRICA PRESENT

## « STORAGE RISKS LOSS PREVENTION A SPECIAL FOCUS ON AFRICA »


By Caroline PAUL – Manager DPS AFRICA November 2022




#### TABLE OF CONTENT

- WHY CHOSE THIS TOPIC
- WHAT MAKES STORAGE THROUGHOUT AFRICA SO PECULIAR
- Different regions, different risks
- Focus on the risks
- THE CORRECT EVALUATION
- THE REASONABLE DOUBT
- THE IMPORTANCE OF DOCUMENTATION
- KEY LESSONS LEARNED
- QUESTIONS AND ANSWERS

## WHY CHOSE THIS TOPIC



WHAT MAKES
STORAGE
THROUGHOUT
AFRICA SO PECULIAR




#### DIFFERENT REGIONS – DIFFERENT RISKS
















## FOCUS ON THE RISKS DRAINAGE CHANNELS

Nigeria





## THE EXAMPLE OF DURBAN – APRIL 2022



















CYCLONES - MOZAMBIQUE







#### **CONSTRUCTION RISKS**











Congo Nigeria Ivory Coast


LACK OF MAINTENANCE



## FIRE RISK - INSTALLATIONS









Mozambique

Senegal

#### FIRE FIGHTING EQUIPMENT






**UGANDA** 





## FIRE - TANK EXPLOSION IN TUNISIA



## FIRE RISK WELDING

Durban – South Africa









# THEFT CIVIL WARS AND UPRISING OF PEOPLE

- PERIMETER WALLS
- CCTV CAMERAS
- PRIVATE SECURITY COMPANY
- ACCESS PROCEDURE
- EXTERNAL LIGHTING
- ANTI-INTRUSION ALARM

#### THEFT - CIVIL WARS - UPRISING OF PEOPLE









#### HANDLING EQUIPMENT





LACK OF TRAINING

STORAGE OF BATTERIES



LACK OF MAINTENANCE



#### REFRIGERATED AND FROZEN PRODUCTS

Electricity failures

Lack of maintenance of the generators in back up

Temperatures - Not remotely controlled and linked to alarms

Few alarms when doors are left opened

Fire suppression system not designed to cope with fire in cold storage areas

No emergency plan in case of cold chain breakdown

No air moisture control

Lack of daily procedure for the control of the temperatures – no temperature chart

During maintenance and repairs, no procedure for reagents to the back up fridge



**NIGERIA** 





WEIGHING EQUIPMENT – STOCK RECORDS





PEST CONTROL – FUMIGATION



## THE CORRECT EVALUATION

STANDARDS







Premier Attraction 343 T/A PREMIER FIRE - PO BOX 76275 | NEW ANDS EAST | 4035 REGISTRATION NO: 2004/069403/23 | VAT NO: 4750265573 39 EATON ROAD, UMBILO, 4001 | 031-205 0548 | 079 411 2716 | www.premier-fire.co.za

#### CERTIFICATE OF COMPLIANCE

This certificate serves to confirm that the Fire Equipment listed below has been serviced, installed and certified in accordance with the South African National Standards (SANS) 10139, South African Bureau of Standards (SABS) 0400, SANS 10400 and SANS 1475 regulations. All work was carried out by SAQCC approved Technicians.

| Type of Equipment  | Qty | Condition | Non conformance |
|--------------------|-----|-----------|-----------------|
| Fire extinguishers | 52  | Good      |                 |
| Fire hose reels    | 9   | Good      |                 |
| Fire hydrants      | 6   | Good      | 0               |

COC issue date : 15-12-2021 Expiry date : 15-12-2022 SABS PERMIT NO : 10264/16218 REG NO : 01/519

Ngubeko Brightman Khuzwayo SAQCC Technician 21/150

THIS CERTIFICATE IS VALID FOR 12 MONTHS ONLY
Copyright - Premier Fire
All rights reserved

#### THE CORRECT EVALUATION

#### BEFORE AFTER













**High Medium And Low Icon with Risk Indicator** 

#### THE REASONABLE DOUBT

#### RECOMMENDATIONS

#### 8. RECOMMENDATIONS

| Item | Recommendations   | State of severity |   | Date of                |
|------|---|-------------------|---|------------------------|
|      |   | High              | Н | planned                |
|      |   | Medium            | М | compliance             |
|      |   | Low               | L | To be planned          |
| А    | Fire assembly points and instructions prohibiting smoking in the warehouse premises be implemented  |                   | н | Immediately            |
| В    | Fumigation procedures and traps should be implemented as one warehouse had insects  |                   | н | Immediately            |
| С    | Drainage channels noted with stagnant water should be maintained  |                   | н | Immediately            |
| D    | More fire extinguishers should be added inside the warehouse, hung on the walls, marked and duly serviced: 15 in warehouse 1 10 in warehouse 2 10 in warehouse 3 Fire hose and standpipes should be installed in front of the warehouse, duly serviced. |                   | н | Immediately            |
| E    | Empty wooden pallets should be evacuated at the end of each working day and stored in a separate building   |                   | н | Immediately            |
| F    | CCTV cameras should be installed inside the warehouses  |                   | L | When possible          |
| G    | The warehouse should be supplied with weighing scales duly serviced/calibrated to avoid relying on weighing done at UGACOF  |                   | м | As soon as<br>possible |
| н    | The walk paths inside the warehouse should be clearly marked  |                   | L | When possible          |
| 1    | A grain temperature and moisture monitoring system and procedure needs to be installed  |                   | м | As soon as possible    |
| J    | Cleaning of the warehouse and rebagging should be done immediately after each operation   |                   |   | As soon as possible    |
| к    | Fire alarms should be installed in the warehouses   |                   |   | As soon as possible    |



#### **DOCUMENTATION**

fire certificate

firefighting training procedure

building maintenance procedure and records

electrical installation control procedure and records:

fumigation certificate and temperature / moisture control of cargoes

business registration certificate

recruitment procedure of the watchmen and employees -

weighbridge last calibration certificate

dangerous goods license

#### KEY LESSONS LEARNED





SIERRA LEONE

## KEY LESSONS LEARNED

EGYPT NIGERIA










## KEY LESSONS LEARNED

#### SOMALIA













### CONCLUSION

